GOVERNMENT OF ANDHRA PRADESH ABSTRACT

Secretariat Buildings – General Administration Department – Repairs to the 500KVA dry type transformer of 'A' Block substation which is standby arrangement to 'C' Block in the premises of A.P. Secretariat, Hyderabad – Administrative Sanction – Orders – Issued.

GENERAL ADMINISTRATION (SB.I) DEPARTMENT

G.O.Rt.No. 4486

<u>Dated:27/09/ 2012</u> Read the following:-

From the Superintending Engineer (R&B) Electrical Circle, Hyderabad, Lr.No.AEE1/Sec/320/2012-13/1792, dated: 04.07.2012.

<<<>>>

ORDER:

In the circumstances reported by Superintending Engineer (R&B) Electrical Circle, Errammanzil, Hyderabad in the reference read above and after examination of the matter, Government hereby accorded administrative sanction for an amount of Rs.3,55,000.00 (Rupees Three lakhs fifty five thousand only) towards repairs to the 500KVA dry type transformer of 'A' Block substation which is standby arrangement to 'C' Block in the premises of A.P. Secretariat, Hyderabad on the responsibility of Superintending Engineer (R&B) Hyderabad subject to following due procedure and also subject to production of the work done certificate at the time of issue of L.O.C.

- 2. The expenditure shall be debited to the head of account "2059 Public works 01 Office buildings MH 053 Maintenance and repairs SH (10) Buildings of General Administration Department 270 Minor works 272 Maintenance"
- 3. This order does not require the concurrence of Finance Department as per rules in force.

(BY ORDER AND IN THE NAME OF THE GOVERNOR OF ANDHRA PRADESH)

AJAY MISRA PRL. SECRETARY TO GOVT. (POLL.)

To

The Superintending Engineer (R&B), Errammanzil, Hyderabad The Electrical Engineer (General), R&B, AC Guards, Hyderabad. The Dy. Executive Engineer (Electrical), Sectt. Sub-division, Hyderabad. SF/SC.

// Forwarded : : By Order //

SECTION OFFICER